



Public ISO 50001 Energy Management System Certified Supplier List

Supplier Name	Facility Locations	Issuing Unit
Micron	Taichung (FAB16), No. 369, Sec 4, Sanfong Rd, Taichung City TWN, 42152, Taiwan (ROC)	TUV
	Taichung (MTB), No. 88, Houke S. Rd., Houli Dist., Taichung City, 42152, Taiwan (ROC)	TUV
Western Digital	No. 388, Jiang Chuan East Rd., Min Hang Dist., Shanghai, China 200241	CNAS/CESI
Samsung	Onyang, 158, Baebang-ro, Baebang-eup, Asan-si, Chungcheongnam-do, 31489 South Korea (ROK)	DQS
	Cheonan, 465, beonyeong-ro, Seobuk-gu, Cheonan-si, Chungcheongnam-do, 31087, South Korea (ROK)	DQS
Intel	Intel Products (Vietnam) Ltd. Lot I2, D1 Road, Saigon HiTech Park Thu Duc City, Ho Chi Minh City, Vietnam	NSAI
	Intel Technology Sdn. Bhd. Bayan Lepas Free Industrial Zone Phase 3, Halaman Kampung Jawa, Penang, 11900 Malaysia	NSAI
	Intel Products (M) Sdn. Bhd. Intel Technology Sdn. Bhd. Kulim Hi-Tech Park, Kulim, Kedah, 09090 Malaysia	NSAI
	Intel Products (Chengdu) Ltd., No. 8-1 Kexin Road Chengdu High-Tech Zone (West Park) Chengdu City, Sichuan Province, China 611731	NSAI
SK Hynix	I-Cheon Plant, 2091, Gyeongchung-daero, Bubal-eub, Icheon-si, Gyeonggi-do, 17336, South Korea (ROK)	bsi
	Cheong-ju Plant, 215, Daesin-ro, Heungdeok-gu, Cheongju-si, Chungcheongbuk-do, 28429, South Korea (ROK)	bsi
Seagate	Wuxi, No. 2, Second Xingchuang Road, Wuxi Export Processing Zone B, Wuxi, Jiangsu Province, People's Republic of China	DNV
	Johor, Plo 55, Jalan Persiaran Teknologi, Taman Teknologi Johor, Senai 81400, Johor, Darul Tanzim, Malaysia	DNV
Nvidia	10018624, Data Center 1, Santa Clara, CA, 95051, USA	DQS
	10018626, Data Center 3, Reno, NV, 89501, USA	DQS
Acbel	No 159, Sec 3, Danjin Rd., Tamsui Dist., New Taipei City, Taiwan (ROC)	TAF/SGS
LG Display	Paju Plant, 245, Lg-ro, Wollong-myeon, Paju-si, Gyeonggi-do, 10845, South Korea, (ROK)	bsi
	Gumi Plant Factory #1, 209, 3 Gongdan-2ro, Gumi-si, Gyeongsangbuk-do, 39394, South Korea, (ROK)	bsi
	Gumi Plant Factory #456, 174, 3 Gongdan-2ro, Gumi-si, Gyeongsangbuk-do, 39401, South Korea, (ROK)	bsi
MSI	No. 37, Tangtou Ave., Tangtou Community, Shiyao Sub-district, Baoan District, Shenzhen City, Guangdong Province, China	CNAS/CQC